

Front View


Rear View




Left Side Right Side Interior broken out ☐ Add-ons Loose/broken/delaminated Missing Previous repair Replaced piece Spindles not original to desk ■ Inscriptions Damage/wear/hole

Top











Bottom


Bottom





Drawer Front, Outer Surface


Rear Surface of Drawer Front














Inside Surface of Left Drawer Side

Inside Surface of Right Drawer Side



Loose/broken/delaminated
Damage/wear/hole

Previous repair

Replaced piece


Missing


Spindles not original to desk

Add-ons

Rear Surface of Drawer Back

Front Surface of Drawer Back





Loose/broken/delaminated
Damage/wear/hole

Previous repair

Replaced piece


Missing


Spindles not original to desk

Add-ons

Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom





Loose/broken/delaminated

Previous repair

Spindles not original to desk

Missing


Add-ons


Damage/wear/hole


Replaced piece

utside Surface, Right Drawer Side

Outside Surface, Left Drawer Side











Damage/wear/hole

■ Replaced piece

Spindles not original to desk